ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 6 | Thanisandra |

| Street ID | Street Name | Significant Landmark |
|---|---|---|
| W0073, W0020, W1947, W1899, W1913, W1945, W1895, W | NA, 4th Crs, 11th Crs Brundavan Lyt Rd, Ambedkar Colony, Venkatramappa Lyt, 3rd Crs, Brindavan Avenu | Nagawara |

| Segment No. | Total Length (m) |
|---|---|
| 6/C-W0073/S052116 | 635.23 |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 234.14 | 77.632053 | 13.069976 | 77.632034 | 13.067860 | Hegadenagara Govt school | MCECHS main road |
| 2 | 401.09 | 77.622104 | 13.039258 | 77.618842 | 13.040810 | Nagawara Bengaluru one center | main road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to sanitary works at Manjunatha Layout, Nagawara, Nagawara colony in ward no. 06 Thanisandra. | 7500000 | 2017-18 |

| Year | Type of Work | Other Work Type |
|---|---|---|
| 2017 - 2018 | Others | Sanitary work |

| Tender | Work Details | Job No. / Work Code |
|---|---|---|
| Not a Tender | Sanitary work | 006-18-000024 |

| Work Order No. | Work Order Date | Period of Extention |
|---|---|---|
| BBMP/EE/BTP/WO/68/2017-18 | 07/02/2018 | |

| Defect Liability Period From | Defect Liability Period To | Multiple road involved with the same Job No/ Work Code # |
|---|---|---|
| 07/02/2018 | 07/02/2019 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| KRIDL | | 0.00 |

| Phone No. | E-Mail ID |
|---|---|
| 9900333496 | |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0073, W0020, W1947, W1899,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | daramsingh |
| **Date of Inspection** | **Remarks** | |
| 23/08/2018 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition |  | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | R.L.Parameshwaraiah | 25/08/2018 | 22/09/2018 | As proposed |
| SE | Vasu K M | 24/08/2018 | 22/09/2018 | Completed |
| EE | Mohandas H.T | 23/08/2018 | 22/09/2018 | completed |
| AEE | Sridhar | 23/08/2018 | 22/09/2018 | completed |
| AE | Daramsingh C naik | 23/08/2018 | 22/09/2018 | Mobile verification is done |
| AE | daramsingh | 23/08/2018 | 22/09/2018 | Forwarded |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0073, W0020, W1947, W1899, W1913, W

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-26

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಕಾರಿಗಳು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ